



	DECIMAL	M M		DECIMAL	M M
	$\frac{1}{64}$ — .0156	0.396		$\frac{33}{64}$ — .5156	13.096
$\frac{1}{32}$	$\frac{3}{64}$ — .0312	0.793	$\frac{17}{32}$	$\frac{35}{64}$ — .5312	13.493
	$\frac{5}{64}$ — .0468	1.190		$\frac{37}{64}$ — .5468	13.890
$\frac{1}{16}$	$\frac{7}{64}$ — .0625	1.587	$\frac{9}{16}$	$\frac{39}{64}$ — .5625	14.287
	$\frac{9}{64}$ — .0781	1.984		$\frac{41}{64}$ — .5781	14.684
$\frac{3}{32}$	$\frac{11}{64}$ — .0937	2.381	$\frac{19}{32}$	$\frac{43}{64}$ — .5937	15.081
	$\frac{13}{64}$ — .1093	2.778		$\frac{45}{64}$ — .6093	15.478
$\frac{1}{8}$	$\frac{15}{64}$ — .125	3.175	$\frac{5}{8}$	$\frac{47}{64}$ — .625	15.875
	$\frac{17}{64}$ — .1406	3.571		$\frac{49}{64}$ — .6406	16.271
$\frac{5}{32}$	$\frac{19}{64}$ — .1562	3.968	$\frac{21}{32}$	$\frac{51}{64}$ — .6562	16.668
	$\frac{21}{64}$ — .1718	4.365		$\frac{53}{64}$ — .6718	17.065
$\frac{3}{16}$	$\frac{23}{64}$ — .1875	4.762	$\frac{11}{16}$	$\frac{55}{64}$ — .6875	17.462
	$\frac{25}{64}$ — .2031	5.159		$\frac{57}{64}$ — .7031	17.859
$\frac{7}{32}$	$\frac{27}{64}$ — .2187	5.556	$\frac{23}{32}$	$\frac{59}{64}$ — .7187	18.256
	$\frac{29}{64}$ — .2343	5.953		$\frac{61}{64}$ — .7343	18.653
$\frac{1}{4}$	$\frac{31}{64}$ — .250	6.350	$\frac{3}{4}$	$\frac{63}{64}$ — .750	19.050
	$\frac{33}{64}$ — .2656	6.746		1.000	25.400
$\frac{9}{32}$	$\frac{35}{64}$ — .2812	7.143	$\frac{25}{32}$		
	$\frac{37}{64}$ — .2968	7.540			
$\frac{5}{16}$	$\frac{39}{64}$ — .3125	7.937	$\frac{13}{16}$		
	$\frac{41}{64}$ — .3281	8.334			
$\frac{11}{32}$	$\frac{43}{64}$ — .3437	8.731			
	$\frac{45}{64}$ — .3593	9.128			
$\frac{3}{8}$	$\frac{47}{64}$ — .375	9.525			
	$\frac{49}{64}$ — .3906	9.921			
$\frac{13}{32}$	$\frac{51}{64}$ — .4062	10.318			
	$\frac{53}{64}$ — .4218	10.715			
$\frac{7}{18}$	$\frac{55}{64}$ — .4375	11.112			
	$\frac{57}{64}$ — .4531	11.509			
$\frac{15}{32}$	$\frac{59}{64}$ — .4687	11.906			
	$\frac{61}{64}$ — .4843	12.303			
$\frac{1}{2}$	$\frac{63}{64}$ — .4843	12.303			
	$\frac{64}{64}$ — .500	12.700			